




Piper Electric Trim – PET-1  
Ray Liles – N316X  
01/17/11





Note the different heights of the roller guides and the routing of the cable through the capstan. Make sure you have correct cable routing and height grooves, when reinstalling the unit.






Stock cork gasket used to make clutch plate with aviation adhesive









Note condition of brushes -- they may require replacement